

NOTICE TO RESIDENTS

100 & 200 BUILDINGS

There have been several instances recently of washing machines vibrating excessively during the wash cycle, resulting in the machine moving out of position and into the laundry room. This is a dangerous situation that could result in flooding, electrical issues, damage to the machines and laundry room, and possibly person injury.

TediMatts, our commercial laundry provider at Condo 1, has confirmed it is highly likely that overloading the washer is the cause of the excessive vibration and movement of the machine during the wash cycle. Examples of overloaded machines include combining a large bedspread with other items in the same wash, or filling the machine with items that extend beyond the top of the washing drum. A very small load could also cause the washer to vibrate excessively.

IT IS EXTREMELY IMPORTANT THAT ALL RESIDENTS USE CAUTION WHEN LOADING WASHING MACHINES:

- **DO NOT FILL THE WASHER WITH ITEMS THAT GO ABOVE THE RIM OF THE WASHER'S DRUM.**
- **DO NOT OVERLOAD THE WASHER BY COMPRESSING ITEMS INTO THE DRUM.**
- **DO NOT WASH LARGE ITEMS SUCH AS BEDSPREADS, WINDOW CURTAINS, OR MULTIPLE SETS OF SHEETS ALONG WITH OTHER LAUNDRY ITEMS. WASH LARGE ITEMS IN A SEPARATE LOAD OR USE A COMMERCIAL LAUNDRAMAT. AVOID VERY SMALL LOADS AS WELL.**
- **CONSIDER RUNNING SEPARATE WASHES IF THERE IS ANY DOUBT ABOUT POSSIBLY OVERLOADING THE MACHINE.**

Please follow the rules for use of the laundry facilities that are posted on the bulletin board in each laundry room. Any resident who is responsible for damage to a washing machine, laundry room or flooding of the building will be held financially responsible for the damage caused by their failure to follow the rules.